
















HUGO krovat' 160x200



NO	Dim.		Col.-No	Qty
1	1644	984	2	1
2	2000	250	1	1
3	2000	250	1	1
4	1610	284	2	2
5	200	2000	1	2
6	200	2000	1	1
7	1644	252	2	1
8	80	1610	2	1
9	1644	67	2	1
10	984	50	1	1
11	984	50	1	2
12	984	50	1	1
13	1344	266	3	1









HUGO krovat' 160x200

K2 x16		ZX x15	 ø7x50	G5 x12		G2 x1		T1 x8		K3 x8	 USØ3,5x30
K1 x3	 UsØ4x30	B4 x16		B5 x16	 ø15x12	M1 x3	 20x20mm	A1 x8	 ø8x30	D10 x6	 USØ3,5x16
O1 x6	 UsØ4x45										







HUGO krovat' 160x200




1






2




HUGO krovat' 160x200


B4		M1		D10	
x4		x3	20x20mm	x3	USØ3,5x16


3



4






G5	
x4	





HUGO krovat' 160x200


5

D10		O1	
x3	USØ3,5x16	x6	UsØ4x45




6


ZX		G5	
x6	Ø7x50	x4	





HUGO krovat' 160x200

7


K2	
x4	


T1	
x2	

K3	
x5	USØ3,5x30












8

ZX	
x4	ø7x50










HUGO krovat' 160x200

9




10




HUGO krovat' 160x200

11



12

K1	
x3	UsØ4x30

